Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: PEOPLES GAS LIGHT AND COKE CO.	Operator ID#: 15329
Inspection Date(s): 11/5/2014, 11/6/2014, 11/7/2014	Man Days: 3
Inspection Unit: North Shop	
Location of Audit: Chicago	
Exit Meeting Contact: Ted Lenart	
Inspection Type: Design Testing and Construction	
Pipeline Safety Representative(s): Steve Canestrini	
Company Representative to Receive Report: Tom Webb	
Company Representative's Email Address: TJWebb@peoplesgasdelivery.com	

CONSTRUCTION INFORMATION			
Location of Construction:	Construction	Performed By:	
5600 block W. Montrose	K&S Energy		
Contractor Foreman:			
Operator Inspector:			
	Person(s) On Job Site		
Bryan Ezerniak	Izidio Llanito	Ean Elderbrook	
Jaud Madula	Allan Lidlow	Jason Taylor	
John Wilgosiewicz	Justin Maldonado		
Description of Construction:			

K&S Energy installing a 4" PE main on the 5600 block of Montrose, via the open trench method

	MAIN INSTALLATION	Status
[192.55]	Steel	No
[192.59]	PE	Yes
[192.59]	Other	No
[192.5]	Class location :	4
[192.619,192.621,192.623]	MAOP	25 PSIG
[192.63]	Pipe Size :	4"
[192.55,192.59]	Specification:	PE 2406/2708

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.55,192.59]	Manufacturer :	DriscoPlex
[192.55,192.59]	Pipe Grade :	D2513
[192.55,192.59]	Wall Thickness :	0.5"
[192.63(a)(2)]	Are pipe, valves, and fittings properly marked for identification?	Satisfactory
General Comment:		
All pipe and fittings observed were properly marked for i	dentification	
[192.227]	Date of Welder qualification:	Not Applicable
General Comment:		
PE main		
[192.227]	Welder's Name:	Not Applicable
General Comment:		
PE main		
[192.225,192.275,192.277,192.279,192.283]	Is pipe joined in accordance with approved written procedures?	Satisfactory
General Comment:		
The fusion operator followed the proper alignment, clear	ning, fusing, and cool down procedures	
[192.285]	Date of Plastic Joining Qualification :	7/18/14
[192.285]	Joiner's name:	Justin Maldonado
[192.455]	Is buried metallic pipe coated?	Not Applicable
General Comment:		
PE main		
[192.461]	Does coating meet 192.461?	Not Applicable
General Comment:		
PE main		
[192.455(a)(1)]	Is cathodic protection being provided?	Not Applicable
General Comment:		
PE main		
[192.455(a)(1)]	Is cathodic protection being provided? By Anodes:	No
[192.455(a)(1)]	Is cathodic protection being provided? By Rectifier:	No
[192.461(c)]	Is coating inspected just prior to being installed in the ditch?	Not Applicable
General Comment:		
PE main		

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.467]	Are pipelines electrically isolated from other underground metallic structures?	Not Applicable
General Comment:		
PE main		
[192.479]	Are above ground facilities cleaned and coated or jacketed as needed?	Not Applicable
General Comment:		
All pipe was installed below grade		
[192.303]	Are comprehensive written construction specifications available and adhered to?	Satisfactory
General Comment:		
A copy of the construction specification	s were on the job site, and were being followed.	
[192.305]	Are inspections performed by the operator to check adherence to the construction specifications?	Satisfactory
General Comment:		
A contract inspector for Peoples Gas w	as on the job site.	
[192.307]	Is material being visually inspected at the site of installation to ensure against damage that could impair its serviceability?	Satisfactory
General Comment: Staff did identify some damage along the within the operator's guidelines.	ne bottom of a section of the 4" main. The fusion operator checked the damage with a depth gaug	e, and found it to be
[192.319]	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Satisfactory
General Comment:		
The ditch was back-filled to provide sup	pport to the main, and free of material that could damage the pipe.	
[192.321(c)]	Is plastic pipe installed as to minimize shear and tensile forces?	Satisfactory
General Comment:		
The pipe was installed in the open trend	ch, which did not apply any force against the pipe.	
[192.321(e)]	Does plastic pipe have means of locating while underground?	Satisfactory
General Comment:		
A tracer wire was installed next to the n	nain. This wire was connected to the tracer wire of the existing main.	
[192.325]	Are required clearances from underground structures being maintained?	Satisfactory
General Comment:		
The main was crossing a telephone due	ct on the N/E corner. The main was being lowered to meet the required clearance.	

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.327]	Is required cover being obtained appropriate to type of pipeline and location?	Satisfactory
General Comment:		
The main was approximately 36" in depth.		
[192.503]	Are general testing requirements being met?	Not Checked
General Comment:		
No pressure test was performed at this time.	Still in the process of installation.	
[192.517]	Are records being made of strength and leak tests?	Not Checked
General Comment:		
No pressure test was performed at this time.	Still in the process of installation.	
[192.807]	Were covered employees Operator Qualification records reviewed to ensure qualification?	Satisfactory
General Comment:		
Reviewed the OQ records for the employees of	on the job site. All were qualified in the tasks assigned.	
[192.805(c)]	Were non-qualified personnel being directed and observed by a qualified individual?	Not Applicable
General Comment:		
All employees on the job site were qualified in	the tasks assigned.	
[192.805(c)]	Were span of control limitations being followed?	Not Applicable
General Comment:	·	
All employees on the job site were qualified in	the tasks assigned	
Was a Protocol 9 (Form 15) Complet	ed?	No
[192.614]	Were One Call Notifications performed as required?	Satisfactory
General Comment:		
Reviewed the dig and permit for the job site. I	Both were valid for the date and location.	
[192.614]	Dig Ticket #	475540134
[192.751]	Are adequate steps taken to minimize the potential for accidental ignition?	Satisfactory
General Comment:	· · · · · · · · · · · · · · · · · · ·	
Warning signs were placed near the construct	ion area. A fire extinguisher was present near the fusing operations.	
[192.719(b)]	Was each repair made by welding to a transmission line made in accordance with 192.713, 192.715, and 192.717 and examined in accordance with 192.241?	Not Applicable
General Comment:		

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

PE main installation

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.